

LOROWERK K. H. Vahlbrauk GmbH & Co. KG

PO Box 1380 D- 37577 Bad Gandersheim Tel.: 05382-71-0, Fax.: 05382-71297 E-mail: drainjet@lorowerk.de Internet: http://www.loro.de

LORO - Flat Roof Drainage with Siphonic Flow

Inspection and maintenance measures

(based on DIN 1986-3:2004-11)

No.	Plant section	Measure	Implementation	Time span
1	Pipeline system	Inspection	Visual inspection of all visible lines for condition, tightness, fastening	1 year
2	Cleaning caps	Inspection	Visual inspection for condition, tightness	1 year
3	Roof drains and emergency overflows / emergency drains	Inspection, maintenance if necessary	Checking for unobstructed inflow and outflow of rainwater. Cleaning of Drains with the superstructures used (e.g. Drainjet bonnets, gravel traps, etc.), Inspection chambers, screen basket with sieve cover, air sieves and sieve units) Missing or defective parts must be replaced. If necessary, check the function of the heating.	6 m onths or as needed in shorter periods, especially in autumn

It is recommended that plant owners use the following for the regularly

The following table shows the number of inspections and maintenance work to be carried out by a specialist company.